## **PIX-** Accessory Products

#### **PIX-X'slit Belt Cutting Machine**



Designed for cutting individual Timing Belts as well as V-Ribbed Belts from the sleeve.

Product code: TTMBCZZZZ000

Price: POA

#### **PIX-Belt Length Measure**



Used for checking the length where size on the Belt is not clearly visible.

Length Measure Conventional (100")
Product code: TLMLMZZZZ000, Price: POA

Length Measure Conventional (120")
Product code: TLMLMZZZZ001, Price: POA

Flat-pulley Length Measure (120")

Product code: TLMLMZZZZ004, Price: POA

### **PIX-Digital Tension Meter**



PIX Digital version of tension meter is used to correct the tension factor in a drive, thus helping the users' to attain the optimum Belt tension.

This equipment works on the frequency measurement phenomenon.

**Product code:** TTTTMZZZZ002

Price: POA

### PIX-X'Align (Laser-guided

Pulley Alignment Instrument)

Robust and highly effective maintenance tool, used to correct the misalignment of pulleys in a drive, to help the user to obtain the maximum service life of the Belt.

Product code: PPG07PWZZ060

Price: POA

## **PIX-** Accessory Products

#### **PIX-Service Kit**



A composite tool kit comprising of vast range of equipment required in maintaining the drive.

The components are housed in a strong ABS outer case, which is light weight, portable and sturdy.

**Comprises of:** PIX-Digital tension meter, vernier calipers, angle gauge, pulley gauges, laser-guided pulley alignment tool, tension tester, measuring tape, torch, calculator, pen and user's guide.

Product code: APIPPAKZZ004

Price: POA

#### **PIX-Tension Tester (Analog)**



Manual tool is meant for correcting or re-tensioning the drive with adequate reliability.

Product code: TTTTMZZZZZ001

Price: POA

#### **PIX-Pulley Gauges**



PIX Pulley Gauges are specially designed for checking the profiles of the grooves of various conventional and dual section pulleys.

Product code: TPUPUZZZZ002

Price: POA

#### **PIX Pulley Gauge for Banded V-Belt drives**



The gauges are a valuable help for measuring grooves of multigrove pulleys for banded-belt sections HA, HB, HC, HSPA, HSPB, HSPC, HAVX10 and HAVX13

Product code: TPUPUZZZZ008

Price: POA

#### PIX-Pentagon (Poly-V Belt Wear Gauge)



PIX-Pentagon is used as wear measurement gauge for Poly-V Belts. Wear in ribs, belt thickness and cracks can be identified using PIX-Pentagon.

Product code: TPUPUZZZZ005

Price: POA

# **PIX-** Accessory Products

#### **PIX-Pentagon (Timing Belt Gauges)**



PIX-Timing Belt Pentagon gauges are specially designed for the inspection of Timing Belt profile.

Product code: TPUPUZZZZ006

Price: POA

#### **PIX-Belt Profile Gauge**



Used for checking the Belt profile.

Product code: TPUPUZZZZ003

Price: POA

